DEC 1951 -- .-

25X1A

U.S. Officials Only CONFIDENTIAL

CENTRAL INTELLIGENCE AGENCY

	INFORMATION REPORT	<u> 25X1A</u>
COUNTRY	Venezuela	REPORT NO.
SUBJECT	Port of Guanta/Barbor Conditions/Stevedoring Services/Warehousing and Tage/Supplies/Repairs/Schedule of Service Trge	RESPONS: VE TO
PLACE ACQU (BY SOURCE	IRED	
DATE ACQUI	RED)	
DATE (OF I	NFO.)	DATE DISTR. 4-JUNE 54
0.5V	THIS OCCUMENT CONTAINS INFORMATION AFFECTING THE MATIGMAL DEFENSE OF THE UNITED STATES. BITMIN THE MEANING OF TITLE IS. SECTIONS 793 AND 794. OT THE U.S. CODE. AS ANEADED. ITS TRANSMISSION OR REVEL. LATION OF TITS CONTENTS TO OR RECEIPT OF AN UNAUTHORIZED PERSON IS FROMIBLED BY LAR. THEREPRODUCTION OF THIS REPORT IS PROHIBITED. THIS IS UNEVALUATED INFORMATION	NO. OF PAGES 3 NO. OF ENCLS. / SUPP. TO REPORT NO.
25X	1X	
SOUR		

The Office of Naval Intelligence fundahed the following information to CIA for IAC dissemination in accordance with paragraph 3(e), NSCID 7. (DIO lIND Conf Reports No 30-54 and 163-54)

- 1. Harbor Conditions and Anchorage: Guanta, which had a population of two thousand in 1949, is the port for Barcelona which has a population of 20 thousand and is the capital of the state of Anzoategui. The port captain allows a maximum draft of 22'6" for a ship berthing on the north side of the dock and a maximum draft of 26'0" for a berthing on the south side of the dock. There is no bar at Guanta, and a depth of five fathoms will be found over the whole harbor. The use of tide is approximately seven inches. There is no swell. There are no buoys to tie up to, but ships can drop one anchor and safely work cargo to lighters. (Sources A and B)
- 2. Dock Facilities: The dock, which is 210 meters long and 13.7 meters wide, is constructed of concrete and steel piling. A 400 to 600 ft extension is contemplated. It is equipped with bits and cleats albernately spaced at about 50 ft. It is raised six feet above low water at the stringpiece. On the dock is a single story warehouse, built of concrete and having steel frames and corrugated zine sheathing. The dock can accommodate one "C-2" type ship and one small "knot" type at the same time. (Sources A and B)

SEE LAST PAGE FOR SUBJECT & AREA CODES

U.S. Officials Only CONFIDENTIAL

DISTRIBUTION -	STATE	RHY.		HAVY		AIR		FBI					
This re	port is for	the use w	vithin the	USA of	the	Intelligence	co	mponents	of t	he Depart	nen	ts or	

Agencies indicated above. It is not to be transmitted overseas without the concurrence of the originating office through the Assistant Director of the Office of Collection and Dissemination, CIA.

CONFIDENTIAL/US OFFICIALS UTLY

- 2 -



- 3. Pilotage: Pilotage is compulsory. Pilots are employed by the Government's Port Service which fixes the fees according to the ship's tennage and the period of the day or night when the services were rendered. /Details are reported in the Schedule of Fees, Charges and Rates, Ports of Guanta and Puerto La Cruz, available on loan from the CIA Library. (Sources A and B)
- 4. Sailing Problems: In 1953 Guanta was considered a very difficult port to enter and leave at night; because of the narrow passage between the shoals between Punta Meta and Punta Queque, which are shown on US Hydrographic Office Chart #5571; and because of the lack of adequate navigational aids. Only the light on Pitahaya was visible when leaving port. The light on Chimana Segunda could not be seen and there was no light at all on the dock. (Source A)
- 5. Lighters: In addition to the lighters available, the Grace Fine has four sectional steel shallow-draft barges with six holds and four water-tight bulkheads. Each has a capacity of 250 tons. Aloca has two pontion lighters, each with a capacity of 150 tons. The only post available in Guanta for towing lighters is Alcoa's 125 hp motor launch, "Manta". (Source B)
 - Berthing: Tugs are not necessary for safe decking and none are available. (Source A)
- Cargo Handling: The law requires that handling of all cargo be done by stevedores of the Government Port Service. The stevedores are government employees, and the government is responsible in case of their injury either aboard ship or on the dock. There are 18 gangs, consisting of 12 men to a gang, available for shipboard work and 16 gangs available for dock work. In October 1952, marine regulations required a special rigging gang to rig gears, take hatches off, and cover up. In October 1952 the stevedores and winch drivers were very good. (Source A) Work is performed on a tonnage basis, 1000 kilos to the ton, loading or discha ging. No gangs are available on Sundays or holidays, as the Port Service does not work. The following are rates of discharge for various types of cargo: flour, cement, rice - 25 tons per hour; steel - 10 tons per hour; cartons of milk - 15 tons per hour; empty bottles and cans - 8 tons per hour; general cargo - 10 tons per hour; pipe - 20 tons per hour; drums of oil and grease - 25 tons per hour; sutomobiles -12 units per hour. All units exceeding eight tons must be discharged directly to vehicles provided by consignees, with whom advance arrangements are made. Units up to 50 tons have been discharged without difficulty. More complete information on stevedoring, customs and consular fees, etc may be found in the "Schedule of Rates, Ports of Guanta and Puerto La Cruz" available on loan ary. / (Source B) Fees, Charges from the CIA Li. ary. 7
- 8. Stevedoring Equipment: The Port Service owns the following cargo handling equipment: 15 tow motors, large, double-wheeled; 8 two motors, medium, single-wheeled; two mobile cranes, 8 ton capacity; 5 mobile cranes, 5 ton capacity; 35 fork trucks, 5 ton capacity; 5 fork-lift trucks, 2½ ton capacity; 6 trailers: 4 tractors; 21 hand trucks; 95 trolleys; 1250 pallets. All of these are in serviceable condition. In addition to Port Service equipment, consigness frequently provide their own (or contracted) vehicles to receive cargo directly from the ship. In Puerto Le Cruz there are about six trucking firms with several hundred vehicles of many types which are suitable for transporting practically any kind of cargo. (Source B)
- 9. Warehousing: A Customs warehouse located on the eastern end of the dock has a floor space of 1170 square meters. Another warehouse on the dock has a floor space of about 1800 square meters. The main floor of the old customs house, which is about 100 meters from the pier, is also used for storage. It has a floor space of about 300 square meters. The Customs warehouse on the dock is used for import cargo. The other warehouse on the dock is used for commissary stores. The storage space in the customs house is used for constwise cargo. (Source B)
- 10. Open Storage Space: There is an open patio measuring approximately 200 meters by 50 meters that is completely paved with asphalt and is currounded by a fence.

CONFIDENTIAL/US OFFICIALS ONLY

CONFIDENTIAL/US OFFICIALS ONLY

~ -3 --

25X1A

It is used for storage of pipe, heavy cases, cement, and drums. West of the dock there is a large unpaved area of reclaimed land which is protected by a fence and the sea. This section is about a quarter of a mile square and is used for storage of pipe, lumber, scrap metal, etc. (Source P)

- 11. Explosives: Upon arrival of a vessel transporting explosives, the agent must inform the authorities of the quality and nature of same. The authorities will then indicate where the cargo must be stored, and discharge must be effected under the supervision of the Guardia Nacional. Explosives are discharged directly from ship to pier. No special magazines for the storage of explosives exist. There are no restrictions covering the transportation of explosives. (Source B)
- 12. Fuel and Supplies: No bunkers are available at Guanta. The nearest bunkers are at Puerto La Cruz. Fresh water can be delivered at the rate of about two tons per hour at a cost of Bolfvars 1.50 per ton. The water is impregnated with calcium. When water is taken on at night, or on Sundays or holidays, the water man is paid an extra fixed-fee of Bolfvars 20.00. Food supplies of all kinds are available in adequate quantities and can be delivered quickly. Fresh vegetables, fish, and meat are abundant. Imported groceries are available. (Source B)
- 13. Ship Repair Facilities: Except for one small ship-way opposite the dock, no facilities exist for repairs of any consequence. However, excellent welding equipment and technicians are available on short notice from Puerto La Cruz, where there are many machine shops. There is no salvage equipment at Guanta. (Source B)
- 14. Transportation Connections: Formerly there was a railroad in this area, but none exists now /January 1954/. An automobile road in good condition connects Guanta with Puerto La Cruz, which is six kilometers away, and with Barcelona, which is 20 kilometers away. There are also connections by automobile roads with San Tome and Caripito. (Source B)

Available on loan from the CIA Library is a typewritten copy of Fees, Charges and Rates charged at Guanta/Puerto La Cruz.

- end -

LERARY SUBJECT & AREA CODES

755.548 8r 756.543 8c 756.545 8c 756.547 8c 756.547 8c 756.544 8c

CONFIDENTIAL/US OFFICIALS ONLI